

002418-002426-0040

Chief Surveyors

Received from Chief Surveyors

SHIP NAME

S.S. "Inwella"

Report

Sl.

No. 43931

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey

1st Entry When due

✦ 100 H1 (Stul)

2 Dks (Stl.)

Call D.B. 342' 9 1/2 t. D.T. a 30' 8 1/2 t. F.P.T. 129 t. A.P.T. 106 t.

F.K. "Intermediate 'tween dk B.H. in forward hold and intermediate 'tween dk B.H. in after hold dispensed with.

4 B.H. to Upper Dk. 2 B.H. to 2nd D^k. Rem. Lloyds A+C.P.

P. 37' B. 171' F. 45'

3/9/21

See letter!

[Signature]

[Signature]

RM
28.8.21

Surveyors should be requested to forward a letter from the Owners regarding the fitting with two 'tween deck bulkheads, in accordance with Inwella No. 11238.

Lloyd's Register Foundation