

18 JUN 1959 4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME BLUEWATER REPORT Nap No. 6796

DBS due 3.59, partly held 2.59, now completed.

CS Advanced.

The Surveyor reports some damage sustained to the starboard outboard auxiliary engine and this engine now out of commission pending repairs. The Surveyor recommends that the class be made subject to the starboard outboard auxiliary engine crankcase being examined and dealt with by the end of May, 1960, meantime the remaining auxiliary engines considered to be sufficient for essential sea services.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of DBS 2.59, subject as recommended.

and fresh record of CS 3.59

[Signature]

3.6.59

*(The Gen)
The boxes should be requested to arrange for the safety valves of the boiler to be adjusted at an early date. This item is outstanding*



© 2021

Lloyd's Register Foundation

002442-002448-0275