

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Screw M.S. "BRITISH RESOLUTION" Rpt. Nwc. No. 95349**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

1st Long. No. 15801Depth "d" --2nd Long. No. 44466Proportions = $\frac{L}{D}$ 13.63Framing Longitudinal framing at bottom
Transverse framing at sidesSheerstrake 1.08
(.98 approved)On account of damage, stated to have been sustained

during launching, the vessel placed in dry dock, bottom cleaned and
coated, repairs effected to bottom shell plating, longitudinals,
bulkhead brackets and minor repairs carried out.

This is a sister ship to the "BRITISH DILIGENCE"

This vessel appears to have been built in accordance with the
Rules and the approved plans, and it is submitted she is eligible to
be classed ☒ **LOCAL 'Carrying petroleum in bulk'**

1 Dk. 2nd Dk. clear of cargo tanks, 'Longitudinal framing at bottom
and at deck'

Cell. DBuE 75' 176t, DTf 34' 397t, FPT 209t, APT 183t.

FK, 17 BH, pt. cem. pt. asp., Lloyd's A & CP.

P 107', B 43', F 45'

Machy. aft.

O.L. 481' - 7"

Handwritten initials
23-8-37

Handwritten initials



© 2020

Lloyd's Register
Foundation

002457-002461-0024

© 2020

Lloyd's Register
Foundation

Register Form	Foundation
CROSS SECTION	
REGISTER	
NAME, STREET	
"	
"	
"	
DE FRAMING	
Frame Anti	
"	
Recessed L	
"	
Depth of L	
Frames in	
"	
"	
Framing in	
Diameter	
State if Fr	
ANTING AN	
TRENGTHEN	
WARD.	
HEIGHT OF	
Floors, De	
H	
Middle Li	
"	
"	
"	
Side Keels	
"	
"	
DOUBLE BO	
Solid Floor	