

19390

on the Machinery of the Wood, Iron or Steel Twin Screw Motor vessel "ANNA KNUDSEN"

9057


Göteborg

Göteborg A/B

N. V. "ANNA KNUDSEN"

List of stores and equipment stowed in the Forehold of the vessel and stated to have been destroyed or damaged beyond repair as a result of the tornado attack on the 5th October 1943.

One 210 cubic foot Lifeboat with 12 H.P. U.S. Marine Motor.  
One Cylinder Liner for Main Motors.  
Two Barrels of Lubricating Oil.  
Two Barrels of Kerosene.  
29 in number Heating Coils for Main Tanks (various sizes).  
300 running feet of 3/4" x 4" x 12" Pineboard.  
6 planks of Pinewood 2 1/2" x 6" x 12" .  
12 planks of Pinewood 2" x 10" x 16" .  
One 200 fathom coil of 3" Manila Rope.  
Two 130 fathom coils of 3" Manila Rope.  
One 120 fathom coil of 10" Manila Rope.  
One 2 1/2" Canvas Hose (Fire Hose) 90 feet long complete with coupling and nozzle.  
One 2 1/2" Rubber Hose 120 feet long complete with couplings and nozzle.  
One 6" Rubber Hose 14 feet long complete with couplings and 12" flanges.  
Two flexible steel Hoses (steam) 50 feet long by 1" complete with couplings.  
Five in number Wire Reels  
Guard Rails belonging to Docking Bridge aft.  
Canvas awning for Poop Deck badly torn and several other awnings damaged.  
200 lbs of pitch.

(Signed) G. MARTIN.Chief Officer.(Signed) L. TORSTENSEN.Master.THE NORWEGIAN SHIPPING & TRADE MISSION  
(SUEZ BRANCH)T. DavidsonT. DAVIDSON  
SUPERINTENDENT CAPTAIN

© 2020

Lloyd's Register  
Foundation

002471-002476-0037

Special Damage or Repair Fee (if any) £ : :  
(per Section 29.)

Travelling expenses (if chargeable) £ : nil

Committee's Minutes

FRI 28 DEC 1945

20/01 1944  
Received by me,  
2/4/ 1944

Engineer Surveyor to Lloyd's