

Rpt. 8

Port FALMOUTH No. 14020

Date of writing Report 18th July, 1961 When handed in at Local Office
Survey held at River Fal No. of Visits 1 First Date and 19 61 Last Date 10th July 61

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 04597 S.S. "BRITISH ADMIRAL" Tons gross 8735
on the Iron or Steel M.S. By Whom Furness S.B. Co. Ltd. Year 1947 Month 1
Built at Haverton Hill Owners' address (If not already in R.B.)
Owners B.P. Tanker Co. Ltd. Port of Registry London
Managers - Date of last examn. in Drydock
Surveyed Afloat or in Drydock Afloat Name of Dock River Fal anchorage.

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 139755 Port LON
To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
<u>100 A1</u>	<u>Oil tanker</u>	<u>LMC-CS</u>	<u>5,55</u>
<u>SS</u>	<u>5,55</u>	<u>d</u>	<u>11,58</u>
<u>DS</u>	<u>11,58</u>	<u>TS(CL)</u>	<u>3,56</u>
		<u>SPS</u>	<u>5,55</u>
<u>LAI D UP - SURVEYS OVERDUE 5,59</u>			

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR TOWING TO PORT IN U.K. IN BALLAST TO BE BROKEN UP

The ship afloat, the shell plating above waterline, decks, hatch and vent coamings, super structures, and casings and all closing appliances, windlass and bower anchors examined and considered satisfactory, for the intended voyage.

The Owners stated that the ship would be towed without main engines or auxiliary power on board and that it was understood that the towing arrangements were not the responsibility of the Society.

Copy of Interim Certificate attached.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

Has a Survey also been held on machinery of the Ship? no
If so, is the Report sent now, or when will it be sent?

Is Classification Certificate required? If so, to be sent to
Has Interim Certificate been issued?

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".


This ship so far as now seen is eligible to be towed to a port in the U.K. in ballast, to be broken up.

K. A. Adamson
Surveyor to Lloyd's Register of Shipping
K. A. ADAMSON.

TUESDAY - 1 AUG 1961

Date of Committee

Minute



© 2020

Lloyd's Register
Foundation

WRKX
5/7.

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR.

SURVEY

Have the spaces now surveyed been cleared and cleaned as necessary?

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined?

Has cement in bottom been examined?

Has steelwork had rust removed and afterwards been recoated as necessary?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held?..... If so, state which

Have the shell and deck plating been drilled as per Rule?

If so, Report 8(Dr) to be attached.

Have any alterations to the approved scantlings and arrangements now been effected?..

If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

The present condition of the following parts in so far as examined is to be reported:—

Have conditions (A) or endorsements (B) of Class (if any) been dealt with?See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee £10. 10. 0.

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable) 5. 0.

Second Surveyor's Fee (if any)

Date when A/c. Rendered 19th July, 1967

© 2020

9th July, 1961.