

REPORT of SURVEY for REPAIRS, &c.

11th Feb 1920

Date of writing Report..... 19²⁰ When handed in at Local Office..... 19..... Port of Copenhagen

No. in Reg. Book. Survey held at Copenhagen " Date, First Survey 21st Jan. Last Survey 27th Jan. 1920.

~~SAILED~~ on the Wood, Iron or Steel Sr. Sr. "Grueborg" (No. of Visits 7. Master J. Rasmussen.

183 TONNAGE:— Built at Rotterdam By whom Wilton's E. & Sperry. Co. When 1919 — 4.

16 GROSS 1908. Owners Dampskibsselsk. "Dannebrog" (C.K. Hansen) Port belonging to Copenhagen

UNDER DE. 1670 Owners' Address.....

NET 1144. (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? *On floating dock* Name of Dock *Leopoldum Dock* Destined Voyage

~~WB = CellDB or DBa~~ 225 feet; uE & B feet; f feet;
total capacity 481 tons. FPT tons; APT 40 tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 70713 Port Rot-

Particulars of Classification (*which must be inserted precisely as in Register Book & Supplements*).

CHARACTER.
 ✕ for Special Survey.
 Date of last Survey and of
 Periodical Surveys.

Years Assigned now expired.	Number of Persons
1	1
2	1
3	1
4	1
5	1
6	1
7	1
8	1
9	1
10	1
11	1
12	1
13	1
14	1
15	1
16	1
17	1
18	1
19	1
20	1
21	1
22	1
23	1
24	1
25	1
26	1
27	1
28	1
29	1
30	1
31	1
32	1
33	1
34	1
35	1
36	1
37	1
38	1
39	1
40	1
41	1
42	1
43	1
44	1
45	1
46	1
47	1
48	1
49	1
50	1
51	1
52	1
53	1
54	1
55	1
56	1
57	1
58	1
59	1
60	1
61	1
62	1
63	1
64	1
65	1
66	1
67	1
68	1
69	1
70	1
71	1
72	1
73	1
74	1
75	1
76	1
77	1
78	1
79	1
80	1
81	1
82	1
83	1
84	1
85	1
86	1
87	1
88	1
89	1
90	1
91	1
92	1
93	1
94	1
95	1
96	1
97	1
98	1
99	1
100	1

Machinery and Boiler
Surveys
(including date of N.B., if any).

400 A1- 4.19

✧ LMC-3.19.

at Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs out of Damage (the cause of which must be stated) should be separated from Repairs due to other causes: these being detailed in the body of the report, should be summarised in the form shown below. Whenever the use of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case. ✓

Society's Freeboard (if assigned) as } 5 3 ft. 0 ins.
painted on Ship and now verified {

the cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? *Services offered, not required* Was a damage report made by anyone else? If so, by whom? ☒

OR EXAMINATION AS PER RULE, FOR

On voyage from Buenos Ayres to Randers the vessel grounded while in the fieth of Randers on the 9th of October 1919.

On the 15th January 1920 the vessel collided with a tug, while in the firth of Rander.

Now dare:-

The vessel was placed on floating dock, bottom and sides were scraped, painted and found good and painted two coats of patent composition. The stem, keel, stern frame and rudder examined and found good. The steam steering engine and its connections, the steering rods, pins, blocks, quadrant and steering gear examined and found good.

[illegible]

Observations, Opinion as to Class, Recommendation, &c.:—

clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon thus, for example:—".....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of" or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptd15, &c."

Recommend the vessel to remain as classed and to have
in of survey 1-20, subject to one frame being renewed at the
convenience.

coin 28) £

Repair Fee (if any) £. 25. 00

es (if chargeable)£

Fee (if any) £

Fees applied for,

11. 2. 1920

Received by me,

.....19.....

Surveyor to Lloyd's Register of Shipping

Committee's Minute

TUE 24 FEB. 1920

Character Assigned

FRI. JUL. *9 1920

Subject

002477-002484-0133

© 2020

Lloyd's Register
Foundation

II On examination found:-

On examination found:-
Two shellplates on starb. side in G and H striae indented.

2 frames in way bent and one do. bent and cracked.

Permanent and temporary repairs now done:-

Starboard Side:-

Starboard Side. -
The No. 14 shellplate in G stroke cut out, faired and reworked, and
the No. 14 do. in H stroke faired in place.

The 3 bent bulwangle frames cut out, faired and reworked.

The cracked bulb angle frame was repaired by electric welding as the profile was not obtainable at the yard at present, but it is the owners intention to have this frame (No. 19 from the after peak bulkhead) renewed at a convenient opportunity. -

Lk.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

[illegible]