

5m, 1, 69

4E

Class is subject to

Weld repairs to corroded centre circumferential rivetted seam of port boiler shell being specially examined as per Berlee Survey.

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME.....

ARENA

REPORT

RDT

No. 50266

Docking

It is submitted that this vessel is eligible to remain as CLASSED.

Subj'd as above



© 2000

Lloyd's Register Foundation

002477-002484-0151