

Report No. ....

# THE BRITISH CORPORATION REGISTER OF SHIPPING AND AIRCRAFT MACHINERY

No. in Reg. Book .....

Port SINGAPORE

S.S. "ASPHALION"

7TH FEBRUARY 194

Survey held\* Afloat at SINGAPORE

Owners A. HOLT & CO (MARS)  
CHINA MUTUAL STEAM NAV CO. LTD. Electric Lighting?        Kws.       

Engines : Description 2 STEAM TURBINES Made by SCOTT'S SB & ENG CO LTD When         
DR GEARED TO 1 SC. SHAFT

Cylinders, No. each Eng.        Diars.        Stroke        Cub. Ft. each L.P. Cyl.       

Boilers : Main, No. & Description        W.P.        Made by        When       

Aux. M. Donkey Do.        W.P.        Made by        When       

Main Steam Pipes, Material        Welded, Brazed, Seamless        When Tested       

Propeller Shaft, Diar. under Liner        Description of Liner        When Drawn       

Class M.B.S.        S.S. Type No.        Due        Boiler Survey Due        M.S. Due       

\* Insert name of Dry Dock ; or where, if afloat.

State if a report on the hull accompanies this report.....

Indicate, clearly, repairs actually carried out and distinguish between those consequent upon damage and those due to wear and tear. All work in connection with special survey must be detailed in the same order as in the rules. State if Boilers (including Donkey Boilers) were examined internally at the same time giving reasons if this has not been done.

First Visit 1.2.49 Last Visit        Boilers and Engines then in        Condition       

No. of Visits       

Fees £        Advised       

Expenses        Paid       

£       

.....Chief Surveyor.



Surveyor to the British Corporation Register  
of Shipping and Aircraft

Lloyd's Register  
Foundation