

002543-002549-0103

Surveyors 1010 18

Received from Chief Surveyors

NAME *Steelers Ravenspoint*

Report *Li*

No. 782 31

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey

When due

Downton pumps dispensed with for duration of the War.

✱ 100 A-1 (Steel) *Shelter Dr with freeboard*

1 Dr (Steel) + *Shelter Dr (Steel)*

Cell DB 216.399C F.P.T. 636-12 P.T. 186-

F.K. *Collision BK to Shelter Dr, 3 BK to upper Dr. Cam - Lenz over.*

ate of Classification, to be endorsed
tens not fitted, ^{in Shelter lower Dr} and the same
e printed in the Register Book.

It is concluded the reinforcement to hulls of shell plating are spaced

3 1/2 inches apart as required by the Surveyors' Rules state of this is so

Aw.

© 2020

Lloyd's Register
Foundation