



4E

Subject to

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

17 DEC 1959

NAME.....ELETRIC.....REPORT.....Off.....No. 60997

MBS due 5.58. Now held and screwshaft examined.

W & T Repairs

The bore of cast iron propeller and the tapered portion of screwshaft found corroded and now satisfactorily machined and refitted.

S.R.L. endorsement

The tap bolts in boiler butt straps specially examined and remain efficient.

IT IS SUBMITTED this vessels machinery is eligible for the records MBS 11.59 and TS (CL) 11.59.


S.R.L. - Appendix Note

Ewh

16.12.59.

S.R.L. - Appendix Note

002543-002549-0154



© 2020

Lloyd's Register
Foundation