

Surveyors

NAME

*St. de ELMWORTH*

Received from Chief Surveyors

Report

*GLS*

No. *52059*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/8/92.)

*1st* No. *2*

SURVEY PARTLY HELD. + *Damage*

*11.32*

When proposed to be completed

Survey held, &c.,


*To complete the Survey:- See Report.*

*Subject to outer plate starboard side repaired by electric welding 12.31 being specially examined at next dry docking.*

*WMA*  
*14-1-32*

*Br*

002577-002582-0200



© 2021

Lloyd's Register  
Foundation