

Received from Chief Ship Surveyor

SHIP'S NAME  
AR.

"FRIVOLITY"

REPORT

Lon.

No. 140070.

29 APR 1959

Standing Conditions of Class:

Subject to indented bottom and side shell plating (p.s.f) and fractured side shell plating (s.s) in way of after side tank being examined and dealt with as necessary next S.S.

Re-issuance of Certificate ~~xx(as before)xx~~ or None)

Place of Present Survey: (At ~~Load and Dry dock~~)

Docking; W & T repairs;

Recommendation:

SUBMITTED record of 'DS 4,59' be assigned, SUBJECT as above;

DS 4,59. Subject.



© 2020

Lloyd's Register  
Foundation

002583 · 002591-0126