

Received from Chief Ship Surveyor

S NAME "ANDREAS G." REPORT Pir. No. 8296

VC

Standing Conditions of Class:

FOR CONDITIONS OF CLASS SEE
ENDORSEMENT DATED 7.3.58.

ACTION is DEFERRED for drydocking and repairs.

Appendix. (As before, or None)
~~xxxxxxx~~

e of Present Survey: (Afloat and in dry dock)

Permanent/deferred temporary damage repairs; S.R.L.

Recommendation: SUBMITTED record of 'DS. 12.59' be assigned as recommended, SUBJECT to set over stem bar and buckled plates A.1 (p & s) also to structure of the cross bunker being dealt with on the ship's arrival at Japan, this tank not to be used as such until repaired and to indented shell plate E.10 (s.s.) being examined and dealt with as necessary at the next drydocking, but WITHOUT other condition.


DS. 12.59. SUBJECT WITHOUT

IN S.R.L. APPENDIX.

Indents in shell plates A.4 & 5
and G.5 (from aft (s.s.))

DELETE FROM S.R.L.

Drydocking (grounding)



002592-008601-0119