

Rpt. 9

Date of writing report 11-1-1962 Received London Port of Amsterdam No. 24594
Survey held at Amsterdam No. of visits 7 First date 28-11-1961 Last date 12-12-1961

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 02519 Name M.V. "ASLAUG TORM" Gross tons 10270 Date of build 1-1953
Owners D/S Torm A/S Managers Axel Kampen & Carl M Andersen Port of Registry Copenhagen
Engines made Aug By Masch. Augsburg - Nurnberg Type oil eng. 2 SA 7 Cy

No. of Main Engines 1 No. of Screws 1
No. of Main Boilers - W.P. -
No. of Donkey Boilers 2 W.P. 171 lb.
Surveyed Afloat or in Dry Dock drydock
Nature of Survey ES(CS) ; Cond & repairs
Was Damage Report issued? - Int. Cert.? -
Last Report (For Head Office only)

Records of Survey & Special Notations as per Register Book

Table with 2 columns: Hull and Machinery. Hull entries include 100 A 1, SS 2/58, oil tanker, d 11/60. Machinery entries include LMC, eng. CS 2/58, boil.d. 11/60, TSCL 11/60, Sps 11/60.

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers good Wear Down of Stern Bushes 2 1/2 mm Oil Glands Sea Connections good
Fastenings good Has Screwshaft Tubeshaft been drawn? Date of Examination Has Shaft been changed?
Has Shaft now fitted been previously used? Has Shaft now examined/fitted a continuous liner? Approved oil gland?

MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD

1 Cyls., Covers, Pistons & Rods
2 Valves & Gears
3 Connecting Rods, Top Ends & Guides 2 + 4 good
4 Crankpins & Bearings 6 good
5 Journals & Bearings 1 and 6 good

MAIN ENGINE DRIVEN AIR COMPRESSORS
6 Cyls., Covers, Pistons & Rods
7 Connecting Rods & Top Ends
8 Crankpins & Bearings
9 Journals & Bearings
10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS
11 Cyls., Covers, Pistons & Rods
12 Connecting Rods & Top Ends
13 Crankpins & Bearings
14 Journals & Bearings
15 Levers

SCAVENGE BLOWERS
16
SUPERCHARGERS
17

MAIN TURBINES
18 Casings, Rotors, Blading, Bearings & Thrusts

EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)
19
STEAM COMPRESSORS
20

CLUTCHES & HYDRAULIC COUPLINGS
21
REDUCTION GEARING
22

THRUST BLOCKS, SHAFTS & BEARINGS good
23
INTERMEDIATE SHAFTS & BEARINGS
24

HOLDING DOWN BOLTS & CHOCKS
25
CONDENSERS (MAIN & AUX.)
26

STEAM RE-HEATERS
27
DE-SUPERHEATERS
28

STOP & MANOEUVRING VALVES
29
MAIN ENGINE DRIVEN PUMPS
30

CRANKCASE DOORS & EXPLOSION RELIEF DEVICES Have Main Engines been tested working and manoeuvring?
31

OPINION OF MACHINERY AND RECOMMENDATIONS
For the information of the Committee.

Date of Committee THURSDAY 5 MAR 1962
Decision See hpi. 8



Has a Survey also been held on Ship? If so, is the Report sent now, or when will it be sent?

If certificate is required state where to be sent

32 Essential Independent Pumps (Identify by position) Lub. oil pump stbd aft; standby fresh/salt coolingw. pump; firepump port forw; bilge and general service pump port forw; both feed pumps : all good.

33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls

34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?

35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)

38 Independent Air Compressors, Coolers & Safety Devices stbd forw. good

39 Air Receivers & Safety devices—Main 40 Auxiliary

41 Oil Fuel Tanks (Not forming part of hull structure)

42 Evaporators 43 Have Evaporator Safety Valves been tested under steam?

44 Steering Machinery 45 Windlass 46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

aux. steam engine port aft : good

ELECTRICAL EQUIPMENT

PROPULSION	PORT	STARBOARD	AUXILIARY EQUIPMENT
a Generators			l Generators & Governors
b Exciters			m Motors
c Air Coolers			n Switchboards & Fittings
d Motors			o Circuit Breakers
e Air Coolers			p Cables
f Control Gear, Cables, etc.			q Insulation Resistance
g Insulation Resistance			r Steering Gear Generators and Motors
h Insulating Oil Test			s Navigation Light Indicators
i Overspeed Governors			
j Magnetic Couplings			
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN **AUXILIARY, DONKEY or PRESS**

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to { Sat.
Spt.

Boiler Securing Arrangements

Main Economisers Exhaust Gas Heated Economisers

Steam Heated Steam Generators Steam Generator Safety Valves Adjusted to

Were Oil Burning System & Remote Controls examined working in accordance with Rules? Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main Auxiliary (over 3 in. bore)

Were Copper Pipes annealed? Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

On the 4th of Dec. 1961 a fire broke out in the engineroom stated to be caused by hot particles dropped whilst burning in the top of the engineroom, the vessel being in the drydock.

The engineroom has been completely flooded to extinguish the fire.

After the engineroom has been provisionally cleaned a general examination has been held on the 12th of December and a preliminary repair recommendation made out. Considerable fire damage to auxiliaries and electrical installation and waterdamage to aux. boilers and main engine were noticed. (Underwriter's surveyors present).

It was learned on the 8th of January 1962 that the vessel will be towed to Antwerp for breaking up purposes.

LEAVE THIS SPACE BLANK

Survey fees f. 250,--

Boilings fees

Expenses " 41,50

Date when A/c rendered 7/2/1962

PLC

