

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

15 JUN 1959

IE FULHAM II

REPORT

NWC

No. 11 6292

5. due 5:59 now held
due 4:59 now held

ing The Surveyor Reports some repairs
to main Boiler & Screw shaft.

He also reports that on account of
the repairs required the Owners have
decided to dispense with the Donkey
Boiler service, and the Safety Valve
chest has been removed ashore.

NOTE FOR R.B.

Delete dt. 00lbs.

It is submitted that this
vessel is eligible for THE
RECORDS.

M.B.S. 6:59
T.S. 8:59



Lloyd's Register
Foundation

002620-002630-0041