



LLOYD'S REGISTER OF SHIPPING

RECEIVED UNITED WITH THE BRITISH CORPORATION REGISTER

18 JUL 1951 Lloydgebäude, Papenstrasse, Bremen

Telegrams: ~~Surveyors, Bremen~~

16th July, 1951.

Telephone: No. 27 649

Dear Sir,

S.S. "CROSTAFELS"/Rpt.No.197

Reference

S

I am in receipt of your classing letter of the 10th inst., and have to state that the stem, shell plating, frames and breast hooks and riveting in way were specially examined and found or placed in efficient condition. Two breast hooks were renewed and peak tank tested and found satisfactory. In my opinion this defect may be repaired at Owners' convenience, Group "B".

I confirm that the shell plate 4th below sheer in way of the deep tank starboard side has been renewed.

The indented tank top plating in No.2 Hold was examined internally and externally and found efficient. Nothing was done at this time.

Yours faithfully,

W. H. Allen

For the Surveyors.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

002653-002658-0072

CLASSIFICATION

H

[Handwritten signature]

endorsement dated 29.6.51

see

Antel. R.S.D. 21.7.51 -



© 2020

Lloyd's Register
Foundation