

1

Now CROSTAFELS23

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Stl & TACTICIAN

Report

Lvi

No.

94000

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey

1st Entry

When due

Old Rules

✠ 100 A. I. (Steel).

2 D^{ks} (Stl).

Cell D.B. 362' 1146t, D.T.a 32' 901t, F.P.T. 62t, A.P.T. 24t.

F.K, 8 B.H (1 B.H to 2nd D^k), Cem, Plyds A/CP
P 37', B 137', F 44'.

0000-007658-0080

© 2020

Lloyd's Register
Foundation

It is concluded the thickness of the hull angle frame in way of the bracket floor is as approved. But the Surveyor should be requested to state if this is so.