

4E

20 JAN 1961

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME.....

"FORMA"

REPORT.....

KRH.....

No. 3215..

Docking. Screwshaft examined.

MBS due 10.59. Now partly held.

Boiler examined and about 60 plain tubes and 11 air heater tubes removed for renewal but the Owners state that it is unlikely the vessel will resume service and at the present time do not intend to complete the repairs to boiler. Under these circumstances the Surveyor recommends that the main boiler should not be used until repaired.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh records of TS (OG) 11.60 now subject to main boiler not being used until repaired.



© 2020

Lloyd's Register
Foundation

16.1.61.

002659-002666-0027