

5m,9,60

4E

Class is subject to

30 MAR 1961

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME....."DAPHNELLA".....REPORT.....SNG.....No...14529..

The Surveyor reports an examination made of the propeller with the vessel afloat and one blade found fractured but as the vessel was proceeding to lay up nothing was done at this time and the Surveyor recommends that the class be made subject to the propeller (blade fractured) and the screwshaft outer end (rope around shaft) being specially examined and dealt with as found necessary before the vessel is re-commisioned.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as recommended.

JW

27.3.61.

© 2020

002659-002666-0139 Lloyd's Register Foundation