

"CORILLA"

(Tanker built 2-1939)

(Riveted. Combination Framing)

This tanker was drilled in 12-56 at the last Special Survey and is not due to be drilled until 12-64. However, at the request of the Owner, pre-Special Survey drillings were carried out by the Singapore Surveyor and reported with report 13725.

IT IS SUBMITTED the Surveyors be informed that an examination of the upper deck and shell plating over the cargo tank length, as shown on Singapore Harbour Board's Drawing No. R/1456, indicates that renewals will be necessary at the Special Survey in 12-60 and that these have been indicated in red on the above drawing for their guidance, it being assumed that the drillings are representative of general condition of the plating. Recommendations for renewal of plating outside the cargo tank length and any amendments to the renewals indicated at present, that may be necessary, should be made by them at the time of the Survey.

The Owner should be advised accordingly. At the same time, the Surveyor's attention should be drawn to the fact that pre-survey drillings were carried out by them on this ship in May 1959, and that there are a number of differences between the drillings then reported and the present ones. This has had an appreciable effect on the renewals considered necessary.

*Shiu*

5th April, 1960.

*all*

*[Signature]*



© 2020

Lloyd's Register  
Foundation

002674-00281-0042