

Rpt. 9

Date of writing report Sept. 30, 1958
Survey held at New Orleans, Louisiana

Received London
No. of visits 2

REC'D NEW YORK OCT 6 1958
OCT 1958

NEW ORLEANS, LOUISIANA 9318
Port
First date 11 June Last date 30 June, 1958

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 56174 Name "CEFALU" S.S. Gross tons 5228 Date of build 1930 - 4
Owners Standard Fruit & S.S.Co. Managers Port of Registry Ceiba
Engines made 1930 By Workman, Clark (1928) Ltd. Type Q 4 Cy.

Records of Survey & Special Notations as per Register Book

No. of Main Engines 1 No. of Screws 1
No. of Main Boilers 4 SB W.P. 260 lbs.
No. of Aux./Donkey Boilers - W.P. -
Surveyed Afloat or in Dry Dock afloat
Nature of Survey Compln. MBS
Was Damage Report issued? - Int. Cert.? Yes
Last Report (For Head Office only)

Hull *100A1 with fbd.	*LMC Machinery 8,54
ssMob.(Dr.) 9,54	M 7,57
docking 12,57	OG 12,57 steam pipes 9,54
	*Lloyd's RMC
	RS 3,57
3 lower decks for fruit cargoes.	SRMC 9,54

9274 - N.O.S.


The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

- DOCKING Propellers vessel afloat Oil Glands Sea Connections
- Fastenings Has Screwshaft/Tubeshaft been drawn? Date of Examination Has Shaft been changed?
- Has Shaft now fitted been previously used? Has Shaft now examined/fitted a continuous liner? Approved oil gland?
- MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD
- 1 Cyls., Covers, Pistons & Rods
- 2 Valves & Gears
- 3 Connecting Rods, Top Ends & Guides { Side Centre
- 4 Crankpins & Bearings { Side Centre
- 5 Journals & Bearings
- MAIN ENGINE DRIVEN AIR COMPRESSORS
- 6 Cyls., Covers, Pistons & Rods
- 7 Connecting Rods & Top Ends
- 8 Crankpins & Bearings
- 9 Journals & Bearings
- 10 Coolers & Safety Devices
- MAIN ENGINE DRIVEN SCAVENGE PUMPS
- 11 Cyls., Covers, Pistons & Rods
- 12 Connecting Rods & Top Ends
- 13 Crankpins & Bearings
- 14 Journals & Bearings
- 15 Levers
- 16 SCAVENGE BLOWERS
- 17 SUPERCHARGERS
- MAIN TURBINES
- 18 Casings, Rotors, Blading, Bearings & Thrusts
- 19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)
- 20 STEAM COMPRESSORS
- 21 CLUTCHES & HYDRAULIC COUPLINGS
- 22 REDUCTION GEARING
- 23 THRUST BLOCKS, SHAFTS & BEARINGS
- 24 INTERMEDIATE SHAFTS & BEARINGS
- 25 HOLDING DOWN BOLTS & CHOCKS
- 26 CONDENSERS (MAIN & AUX.)
- 27 STEAM RE-HEATERS
- 28 DE-SUPERHEATERS
- 29 STOP & MANOEUVRING VALVES
- 30 MAIN ENGINE DRIVEN PUMPS
- 31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES

Have Main Engines been tested working and manoeuvring?
OPINION OF MACHINERY AND RECOMMENDATIONS The machinery of this vessel so far as now seen is in good and safe working condition and eligible in my opinion to remain as classed and it is recommended that the record of MBS 5,58 now be made in the Register Book.

Date of Committee NEW YORK OCT 8 1958
Decision As now. MBS 5.58.

Noted for Header



001711-001716-0013

If certificate is required state where to be sent.

- 32 Essential Independent Pumps (Identify by position).....
- 33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls.....
- 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?.....
- 35 Fresh Water Coolers..... 36 Lub. Oil Coolers..... 37 Heaters (state service).....
- 38 Independent Air Compressors, Coolers & Safety Devices.....
- 39 Air Receivers & Safety devices—Main..... 40 Auxiliary.....
- 41 Oil Fuel Tanks (Not forming part of hull structure).....
- 42 Evaporators..... 43 Have Evaporator Safety Valves been tested under steam?.....
- 44 Steering Machinery..... 45 Windlass..... 46 Fire Extinguishing Arrangements.....

AUXILIARY ENGINES (Identify by position).....

ELECTRICAL EQUIPMENT

PROPULSION	PORT	STARBOARD	AUXILIARY EQUIPMENT
a Generators.....			l Generators & Governors.....
b Exciters.....			m Motors.....
c Air Coolers.....			n Switchboards & Fittings.....
d Motors.....			o Circuit Breakers.....
e Air Coolers.....			p Cables.....
f Control Gear, Cables, etc.....			q Insulation Resistance.....
g Insulation Resistance.....			r Steering Gear Generators and Motors.....
h Insulating Oil Test.....			s Navigation Light Indicators.....
i Overspeed Governors.....			
j Magnetic Couplings.....			
k Air Gap.....			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN Starboard After - Good - 11 June, 1958..... AUXILIARY, DONKEY or PRESS.....

Superheaters..... -

Safety Valves..... Good

Mountings, Doors & Fastenings..... Good

Safety Valves Adjusted to { Sat. 260 lbs. p.s.i.
Spt. -

Boiler Securing Arrangements..... Good

Main Economisers..... - Exhaust Gas Heated Economisers.....

Steam Heated Steam Generators..... Steam Generator Safety Valves Adjusted to Yes

Were Oil Burning System & Remote Controls examined working in accordance with Rules?..... Forced Circulating Pumps.....

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?..... Funnel Good

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main..... Auxiliary (over 3 in. bore).....

Were Copper Pipes annealed?..... Have Saturated Pipes in cylindrical boiler smoke boxes been tested?.....

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

Starboard After Boiler
9 cc stays renewed.

LEAVE THIS SPACE BLANK

Survey fees ... MBS (Compln) \$50.00

Damage fee ...

Expenses... 2.00

Date when Alc rendered... 9 September, 1958



© 2020

Lloyd's Register Foundation

Handwritten notes in blue ink: "29. 10. 58", "MBS", "2.00", "9 cc stays renewed".

Handwritten number "246" in the bottom left corner.