

22 JUL 1958

Received from Chief Ship Surveyor

SHIP'S NAME "ESSO HULL" REPORT NWC. No. 115369
AR.

Outstanding Conditions of Class: Subject to sternframe in way of outer plates (E.W. 6,56 & E.W. & reinforced 2,57) being specially examined at next drydocking.

Endorsement of Certificate (~~As before~~ or None)

Signature of Present Survey: (Afloat and in dry dock) Drydocking; W & T repairs; deferred repairs; - indented side shell plating (p & s) on account of damage - cause not stated; sternframe (E.W. 6,56 & E.W & reinforced 2,57), deferred item above, examined and found continues to be efficient.

Recommendation: SUBMITTED record of 'DS 6,58' be assigned as recommended SUBJECT as above and to indented side shell plates J.14 (p.s.a) J.3, H.3, 4 & 5 (p.s.f), H.13 (s.s.a) and J.4 & 5 (s.s.f) being examined and dealt with as necessary by the Special Survey.

DS 6,58. Subject.

Blk(new)