

Date of writing Report 4/11/58

When handed in at Local Office

Received London

24 NOV 1958

Survey held at Penang

No. of Visits 2

First Date 1st Nov 1958

Last Date 2nd Nov 1958

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.

No. in R.B. 62410

on the Iron or Steel S.S.

"GOLDEN BETA"

Tons gross 5389

Built at Glasgow

By Whom

D. & W. Henderson & Co. Ltd.

When

Year 1920 Month 1

Owners

Marine Nav. Co. Ltd.

Owners' address

Managers

World-Wide Co. (Managers) Ltd.

Port of Registry

HONG KONG

Surveyed Afloat or in Drydock Afloat

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 12906

Port SMC

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS		Machinery
Date of Special and of Drydocking Surveys, etc.		
100 A1		L.M.C.
DR 12/46	S.S. 9/55	9/55
Docking	9/57	M 9/57
		CL 9/57
		Steam Pipes 9/55

Give dates and references to any letters relating to this Report.

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined.

Freeboard as marked on ship and now verified ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR A hole was discovered while chipping in Starboard G Strake immediately abaft frame 83 from aft. See Rpt. 10 attached.

Now Done. On 2nd November 1958 a 3/8" thick mild steel doubler 2'6" wide by 4 feet high was fitted with hole in plate at centre and was welded all round. This doubler was hose tested and found sound and tight.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? No

Is Classification Certificate required? If so, to be sent to No

If so, is the Report sent now, or when will it be sent? -

Has Interim Certificate been issued? Yes.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey, for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

It is recommended that the vessel remains as now classed, subject to permanent repairs to plate in Starboard G Strake abreast frames 82 to 84 being effected at vessel's next dry-docking.

Ag. *W. A. L.*
Surveyor to Lloyd's Register of Shipping

Date of Committee

MONDAY - 8 DEC 1958

Minute

As now Subject

Noted for Header

