

JP

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

16th May, 1960.

Dear Sirs,

s.s. "DIMOS"

With reference to the classification of this ship in the Society's Register Book, I would point out that the Special Survey becomes due at the end of June next and I shall be glad to learn what arrangements are proposed for this inspection to be carried out.

As a result of an inspection carried out in drydock at Colombo last February, the Surveyors recommended that set up shell plates C.9 & 10, D.9 & 11, F.4 & 15 and G.4 (port side); A.11, 13 & 15, B.9, 11, 12, & 13, C.11, 13, & 14, D.7 & 9 (starboard side) and structure in way; also No. 5 hold forward longitudinal bulkhead and stiffeners etc. and No. 2 DB tank top plating (fractured) should be specially examined and dealt with as necessary by June, 1960, and your intentions regarding these items would also be appreciated.

I take this opportunity of reminding you that the Main Boiler Survey becomes due at the end of July next.

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Loucas Nomikos (England) Co., Ltd.,
Leadenhall House,
101, Leadenhall Street,
LONDON, E.C.3.

Lloyd's Register
Foundation

002846-002852-0185