

- 4 MAY 1960

SHIP'S NAME "DIMOS"

REPORT Cbo

No 4605

EA

Outstanding Conditions of Class: SUBJECT to No.5 hold fwd, longitudinal bulkhead and stiffeners etc., and to No.2 double bottom tank top in way (fractured) being specially examined and dealt with as necessary by the next drydocking.
ACTION is DEFERRED for examination in dry dock, and repairs after over-riding dredger chain cable by 11.59.

S.R.L. Appendix. (~~As before~~ or None)Nature of Present Survey: (~~Afloat and~~ in dry dock)

DOCKING. Damage (grounding) involving bottom shell plating and internal structure.

Recommendation: SUBMITTED record of DS 2.60 be assigned subject to set up shell plates C.9 & 10, D.9 & 11, F 4 & 15 and G.4 (ps) and A.11, 15 & 13, ~~B.9, 11, 12 & 13~~ B.9, 11, 12 & 13, C.11, 13, 14 and D.7 & 9 (s.s) and structure in way also No.5 hold forward longitudinal bulkhead and stiffeners etc., and No.2 double bottom tank top plating (fractured), being specially examined and dealt with as necessary by 6.60.

DS 2.60 SUBJECT (Amended)

DELETE FROM S.R.L.

Drydocking & repairs (over-riding dredging chain cable) by 11.59.



©

2020
28-4-60Lloyd's Register
Foundation