

COPY.

LLOYDS REGISTER
STOCKHOLM.

(1-12-38)

DURNESS DALNESS YOUR REPORTS 4486 4582 EACH VESSEL HAD BROKEN SCREWSHAFT
STOP NEW SHAFTS AND INTERMEDIATE SHAFTS FITTED QUARTER INCH LARGER THAN
CABLE
ORIGINALLY STOP ~~STATE~~ WHETHER ENGINE MAKERS ATTRIBUTE TROUBLE TO
VIBRATION STRESSES AND WHETHER THEY CONSIDER ALL NOW SATISFACTORY
COMMITTEE.



© 2020

Lloyd's Register
Foundation

002858-002869-0109