

SHIP'S NAME "THELIDONUS" REPORT Cff. No. 61168
 GB

Outstanding Conditions of Class: SUBJECT to portside main deck in way of steering E.R. (buckled) being specially examined and dealt with as found necessary by the Special Survey.

S.R.L. Appendix. (As before or None) ~~or None~~

Nature of Present Survey: (~~Afloat and~~ in dry dock)

Docking: Temporary repairs to wasted shell plate etc.

Recommendation:

SUBMITTED record of 'DS 6,60' be assigned, subject as above, and to wasted shell plate B.6 (s.s.f) also wasted welding in way of after keel plating and rudder side plate being dealt with before the ship is recommissioned.

DS 6,60 Subject
 IN S.R.L. APPENDIX.

Side shell plating (p & s) set in and/or indented.

OFFICE NOTE

Deck and bottom shell reinforced - Cff. 2,53.

Docking brackets fitted - Nwc. 1,54.

NOTE:-The ship is now ^{to be} laid up and it would appear that she will be drydocked for repairs before being replaced in service.

