

"THELIDOMUS"

According to the Liverpool Report No. 127333
to complete the spare gear thrust pads, intermediate shaft
coupling bolts and a propeller should be supplied.

IT IS SUBMITTED the Owners be advised accordingly.

J.H.

24. 9. 48.



© 2020

Lloyd's Register
Foundation

002858-002869-0243