

the screwshaft cone being specially examined by the end of 6.61.

1 - AUG 1961

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

AME....."RUSEN".....REPORT.....IST.....No. 5049.....

SRL.

The above item now dealt with and the Surveyor states no deterioration noted in the condition of the cone since it was last examined and recommends that the item be deleted from the list and that the record of TS (CL) 7.59 be assigned. The Surveyor also recommends that an entry be made in the SRL Appendix relative to this tailshaft cone.

IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh records of TS (CL) 7.59 without special condition.

SRL APPENDIX NOTE.

"Small area of tailshaft cone scolloped out 4" from end of liner".

© (2020) JN

31.7.61.

Lloyd's Register
Foundation

007876-007872-0078