

26 JUL 1949

Ship Surveyor

Received from Chief Ship Surveyor

NAME "ISLE OF GUERNSEY"

REPORT

Sou.

No. 19802

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points entered in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to shell plate F.5 (p.s.a.) being repaired at the next dry docking.

The SOUTHAMPTON Surveyors report (5.49), the vessel placed in dry dock, bottom coated and minor repairs effected.

Repairs effected to shell plate F.5 (p.s.a.), as above.

IT IS SUBMITTED the vessel is eligible to remain as classed, with record of docking survey 5.49, without special condition.

5.49 Sou.

Without,



© 2020

Lloyd's Register
Foundation

002876-002882-0240