

002876-002882-0243

4 E

Engineer Surveyor

Received from Chief Engineer Surveyor

26 JUL 1949

NAME "ISLE OF GUERNSEY" REPORT Sou. No. 19802

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

~~REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH~~

The case of this vessel, which holds a notation of "Classification contemplated", is fully stated in an endorsement dated 2. 5. 49. On account of damage sustained through the starboard propeller striking buoy, The vessel has been examined in dry dock, the starboard propeller shaft drawn and examined, and a new propeller fitted.

The Special Survey for Classification has not been advanced.

IT IS SUBMITTED action be deferred, pending completion of the Classification Survey.

Starboard S 5.49.

See Sou. LW, 2/8/68.



© 2020

Lloyd's Register Foundation

26. 7. 49.