

Received from Chief Ship Surveyor

9 JUL 1959

SHIP'S NAME "JANO"

REPORT LA.

No. 3417

VC

Outstanding Conditions of Class: SUBJECT to a spare bower anchor of Rule weight and test being supplied at the earliest opportunity, and to scrubbed bottom rivets in way of fore peak (p & s) being specially examined and dealt with as necessary next drydocking, and to buckled stem and bow plating and internals in way being dealt with before the end of June 1959,

ACTION is DEFERRED for examination in drydock and repairs after grounding.

S.R.L. — Appendix. (~~As before~~ or None)

Nature of Present Survey: (Afloat and in dry dock)

Examination and temporary repairs after grounding.

Recommendation:

SUBJECT as above, but FURTHER ACTION BE DEFERRED for examination and repairs in drydock.

SUBJECT.

THIS IS A SUBSEQUENT REPORT OF A PREVIOUS SURVEY SEE
ENDORSEMENT DATED 1.6.59.



Lloyd's Register
Foundation