



Lloyd's Register of Shipping,

LLOYD'S REGISTER
LONDON.

RECD^Y 17 JAN 1921

ANS'D ✓

Lloyd's Bank Chambers,

Middlesbrough, 6th. January 1920.

Dear Sir,

In reply to your letter M of the 5th. instant.
regarding our First Entry Report No. 10896 on S.S. "PENTEIFI",
I beg to inform you

- (1). That the side stringers are fitted in the vessel as shewn on the plans.
- (2). Bulkhead No. 70 is watertight to Upper Deck, and not to Awning Deck as stated. The collision bulkhead extends to Upper Deck at frame 121, and between Upper and Awning Decks at frame 117. *Circular*
- (3). The bottom shell plating thicknesses were verified wherever possible clean of cement in double bottom, and also where plating was dealt with for repairs.
- (4). The $\frac{1}{8}$ " diameter rivets in the shell plating butts are spaced $3\frac{1}{2}$ inches apart as shewn on the First Entry Report.

I am, Dear Sir,

Yours faithfully,

J. C. Cocks

© 2020



Lloyd's Register
Foundation

002883-002890-0051

002883-002890-0052

Referred to the Chief Ship Surveyor.

17 JAN 1921

Portion
the second
and the third

Anna A. Lafferty

17 JAN 1921

(a) The port of loading and discharge
and the port of delivery shall be agreed
upon by the parties to whom the
charter party is given.

(b) The port of loading and discharge
and the port of delivery shall be agreed
upon by the parties to whom the
charter party is given.

(c) The port of loading and discharge
and the port of delivery shall be agreed
upon by the parties to whom the
charter party is given.

(d) The port of loading and discharge
and the port of delivery shall be agreed
upon by the parties to whom the
charter party is given.

(e) The port of loading and discharge
and the port of delivery shall be agreed
upon by the parties to whom the
charter party is given.



Lloyd's Register Foundation © 2020