

Rpt. 8

/NP

Port NEWCASTLE UPON TYNE

No.

118975

Date of writing Report 2.7.62.

When handed in at Local Office

4.7.62

Received London

-5 JUL 1962

Survey held at South Shields

No. of Visits 2

First Date 27.6.62. 19

Last Date 29.6. 19

62

## REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

04959

on the Iron or Steel M.S.

"BRITISH ADVOCATE"

Tons gross

8573

Built at Port Glasgow

By Whom

Lithgows Ltd.

When

1948

Owners

Netransmar S.A.

Owners' address

31, Marche Aux Souliers, Antwerp

(If not already in R.B.)

Managers

Port of Registry

London

Surveyed Afloat or in Drydock

Afloat

Name of Dock

River Tyne

Date of last examn. in Drydock

-

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

118931

Port

Mur

To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report.

### SHIP'S CLASS

Date of Special and of Drydocking Surveys, etc.

Machinery

\*100A1

6.61

\*LMC

CS 5.57

Oil Tanker

BS

A 6.61

SS

5.57

CL

5.60

sp

5.57

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft

ins

Was a damage report made by anyone else? If so, by whom? Underwriters

### EXAMINATION AND REPAIRS AS PER RULE FOR Damage Survey

This ship was visited at the request of the Agents on account of damage stated to have been sustained

(1) When vessel broke adrift in the River Tyne on the 24th June, 1962.

(2) Through contact with the m.v. "ACCUM" when the "ACCUM" was undocking at John Readhead's Dry Dock, South Shields on the 27th June, 1962.

### Damage found

(1) Starb. side shell aft in way of steering gear space set in and torn, frames buckled.

(2) Shell aft at stern pierced above aft Peak Tank and below Aft Peak Tank top.

### Temporary repairs carried out.

(1) Watertight doors in bulkhead to steering gear compartment permanently closed by welded lugs.

(2) 2 Patch plates welded over holes in shell plating.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

Has a Survey also been held on machinery of the Ship?

No

Is Classification Certificate required? If so, to be sent to

No

If so, is the Report sent now, or when will it be sent?

-

Has Interim Certificate been issued?

Yes, copy attached.

### GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1.55"; or "to remain as Classed and to have record of drydocking 1.55, and the notation of S.S. . . . 1.55".

This ship, so far as now seen, is fit to be towed as a hulk to Bilbao for breaking up, the classification being suspended.

J. Ballantine  
Surveyor to Lloyd's Register of Shipping  
J. BALLANTINE.

Date of Committee

Minute



© 2020

Lloyd's Register  
Foundation

002897-002906-0022

NWC 12/6

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR

Damage

SURVEY

Items	Now Examined YES NO or NONE	Tanks	Now Examined Internally	Now Tested
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock		F.P. Tank		
Rudder lifted		A.P. "		
Weather Decks, Superstructures and Casings		D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances		Fresh Water Tanks		
Ventilator coamings, skylights, companionways and closing appliances		Deep Tanks		
Holds		Oil Fuel Bunkers and Settling Tanks		
'Tween Decks		Side Tanks		
Fore Peak Spaces		Wing Tanks		
After "		Other Tanks		
Engine Space		Cargo Tanks (Tankers)		
Boiler "				
Under Engines and Boilers				
Tunnel and Well		Cofferdams		
Coal Bunkers		Pump Rooms		
Chain Locker				
Other Spaces				
Have Tanks now Examined been Cleaned as Necessary?				
Have Struts in Cargo Tanks (of Tankers) been removed?				
Have Tanks been Retested as necessary after completion of any Repairs?				

Have the spaces now surveyed been cleared and cleaned as necessary?

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?

Have the bilges been cleaned out and examined?

Has cement in bottom been examined?

Has steelwork had rust removed and afterwards been recoated as necessary?

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?

Has a Load Line Survey been held? If so, state which

Have the shell and deck plating been drilled as per Rule?

If so, Report 8(Dr) to be attached

Have any alterations to the approved scantlings and arrangements now been effected?

If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 &amp; 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating .....	Ceiling and Cargo Battens .....	Sluice Valves examined and found .....
"    "    in way of side scuttles .....	Cement or Asphalt .....	Air and Sounding Pipes .....
Rudder and Sternframe .....	Cargo and other Hatchways .....	Doubling Plates under Sounding Pipes .....
Decks .....	Hatches and closing appliances .....	Masts and Rigging examined and found .....
Superstructures and their closing appliances .....	Ventilators, their coamings .....	Condition, how ascertained .....
Coamings and Casings .....	and closing appliances .....	(State if wedges removed)
Beams and Fastenings .....	Companionways and Skylights .....	Chain Locker .....
Frames .....	Shell Openings .....	<div>EQUIPMENT</div>
Reverse Frames .....	Ash Shoots .....	Equipment Letter .....
Longitudinals .....	Overboard Discharges and Scuppers .....	Anchors, No. of .....
Transverses .....	Freeing ports .....	Condition .....
Floors .....	Steering Gear (Main and Auxiliary) .....	Cables (State if now ranged and examined) .....
Keelsons .....	examined and found .....	"    length .....
Stringers .....	Windlass examined and found .....	"    "

Have conditions (A) or endorsements (B) of Class (if any) been dealt with?

No

See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Date when A/c. Rendered

© 2020

Lloyd's Register  
Foundation  
4 JUL 1962