

NAME "CORYDA" REPORT Sng. No. 12379.

ding Conditions of Class: Subject to rudder back post (B.W. 11,56 & Previously) being specially examined, and to Nos.2 & 3 keel plates (corroded) from fwd. being renewed next drydocking.

ment of Certificate (As before ~~or None~~)

due:

SPECIAL SURVEY(C) due 11,58, commenced Sng. 10,57.

of, Present Survey: (Afloat ~~and in dry dock~~)

Deferred damage repairs.

Features:

im Certificate in order (Yes-~~No~~)

~~standing xxx (xxx) xxx~~

FOR PORTION OF SURVEY HELD: -

See Sng.Rpt.12276.

be completed by:

udation:

SUBJECT as above, and to set in main sheerstrake plates, etc. Nos.3 & 4 (s.s.) from fwd. being examined and dealt with as necessary at the next drydocking.

s Now. Subject.

ENDORSEMENT OF CERTIFICATE.

hell plates E.3, F.2, G.2
t H.1 (s.s.) slightly indented.

S.S.PART HELD.



© 2021

Lloyd's Register
Foundation

002407-002415-0084

BM
27.1.58