

the Surveyor proceeding to inspect each Main Boiler separately and make a thorough examination at this time?

Donkey

yes

ot, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VS NAME

Jalua ex Peik

REPORT

Kel

No. 609.

a remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

It is submitted that before this case receives consideration the Hamburg Surveyors should be requested to forward their first early report on the new main engine No. 49 made by Howaldswerke A.G.

✓ Home Rep. received  
✓ AKS 8/8/52

and removed from vessel.

