



© 2020

Lloyd's Register
Foundation

S/S "CLAN MURRAY"

AT MANILA, 28th OCTOBER/3rd NOVEMBER, 1962.

Forward Boiler Feed Pump Cover, water end, showing the fractured improvised brass bushing, the wasted material in way of the gland stud and the improvised gland cover to hold the fractured gland bushing in position. This cover, (C.I.) had also been previously repaired on the underside.

Refer to Rpt. 4541



Lloyd's Register
Foundation

10/31/62-3

002491-003005-0115