

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME Stl Se. "COLONEL CROMPTON Rpt. Sld No. 31287

Marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

verse No. 4236 Depth "d" 14.93 to U.D.
 ng: Table No. ✓ Description Bulb angle frames as approved
 tudinal No. 13223
 Proportions Length 13.2 to U.D.
 Depth =
~~Beck~~ Sheerstrake as approved

This vessel appears to have been built in accordance with the
 and the approved plans, and it is submitted she is eligible to
 ased

✠ 100 A.1. (Steel).

1 D* (Stl). Well D*

Cell D.B. U E 23' f 162' H25t, D.T. f 142t, F.P.T. 158t, A.P.T. 25t.

F.K, ⁴ S.B.H, pt cem, Lloyd A CP.

Q 145', B 16', F 22'.

machy aft.

ertificate of Classification to
 ed "Cargo battens not
 fitted" and the same notation to be
 printed in the Register Book.



© 2021

Lloyd's Register
Foundation

008024-008057-0020