

Received from Chief Ship Surveyor

16 MAY 1961

NAME "BRITISH ENDEAVOUR" REPORT SLD No. A 43

EA

Working Conditions of Class:

SUBJECT to rudder mainpiece below coupling (E.W. 12,58) being specially examined next drydocking, also to shell plates G.4 & 5 and H.4,5 & 6 (p.s.f) also to H.3 & 4 (s.s.f) being specially examined and dealt with as necessary by the Special Survey.

Appendix. (As before or None)

of Present Survey: (Afloat and in dry dock)

Docking:- Wear and tear repairs.
Examination of deferred items as above.

Condition:

SUBMITTED record of DS 3,61 be assigned, subject to shell plates G.4 & 5, H.4,5 & 6 (p.s.f), H.3 & 4 (s.s.f) being specially examined and dealt with as necessary by the Special Survey, without other conditions.

DS 3,61 Subject
Without



© 2021

Lloyd's Register
Foundation

003079-003075-0199

File
11/5/61