

1038.

Chief Surveyors ..... Received from Chief Surveyors .....

SHIP'S NAME "DONACILLA". Report Gls. No. 61720.

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Part of Survey FIRST ENTRY When due --

Two longitudinal bulkheads fitted.

This is a sister ship to the "CEDARDALE" and "DARINA"

Damage through striking quay wall, fouling fender and collision has been dealt with.

GOAL "Carrying petroleum in bulk"

1 Dk, 2nd Dk. clear of cargo tanks, "Longitudinal framing at bottom and at deck"

Cell DBuE 70' 165t, DTf 25', 297t, FPT 143t, APT 89t

FK, 17BH, Lloyd's A & CP.

P 93' B47' F 51'

Machy.aft.

O.L= 482.8'

E.S.D.

"ct"

*f.c.D*

*[Signature]*



10.11.39.



© 2020

Lloyd's Register Foundation

003046-003055-0301