

See Endorsement dated 23.10.59.

Received from Chief Ship Surveyor

9 NOV 1959

SHIP'S NAME "DONACILLA"

REPORT

Sng.

No. 13526

Outstanding Conditions of Class:

// internal structure in way fr.100 (s.s.) and to shell plates C.14 (scored & doubled) and D.12 (fractured and doubled) (p.s. from aft) also H.3 (wasted & doubled) (p & s) being specially examined and dealt with as necessary by the S.S.

S.R.L. Appendix. (As before ~~or None~~)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to starboard hawse pipe (fracture).

Recommendation:

// SUBJECT as above, and to starboard hawse pipe (fractured) being renewed by the Special Survey.

As Now. Subject

IN S.R.L. APPENDIX.

Indents in stem plating and a few shell plates (p & s).



2/11/59  
© 2020

Lloyd's Register  
Foundation