

P'S NAME "GOLDEN ALPHA" REPORT Kob. No. 6464.
AB.

standing Conditions of Class: Subject to shell plates H.9 (p.s) and G.15 (s.s. from aft) (wasted, fractured & doubled) being permanently repaired and adjacent shell plating being specially examined internally next drydocking.

ACTION IS DEFERRED for examination in drydock after grounding.

orsement of Certificate (~~As before~~ None)

ure of Present Survey: (Afloat ~~and in drydock~~)

Recommended repairs to fractured shell plate on account of H.W. damage.

Not effected because Owners state that ship will be sold for breaking up at this time.

ommendation:

SUBJECT as above and to fractured shell plate No.2 (p.s.f) 2nd below sheer being repaired before ship proceeds to sea, but ACTION CONTINUE TO BE DEFERRED for examination in drydock after grounding.

Subject, amended.

IN S.R.L.
Drydocking (grounding).



© 2020

Lloyd's Register
Foundation