

"DIANA"

Nap. " 7446 "

Before this case receives consideration the Surveyor should be requested to state whether the auxiliary steam pipes above 3" bore if, fitted, were examined and found satisfactory, also as the survey is incomplete pending the saturated steam pipes in the cylindrical boiler smoke boxes being dealt with. An amended interim certificate should be issued.



© 2020

16/7/62

Lloyd's Register
Foundation

003692-003099-0220

4m,5,62

Class is subject to

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "DIANA" **REPORT** Nap. **No.** 74

Before this case receives consideration the Surveyor should be requested to state whether the auxiliary steam pipes above said 12" pipe is fitted, were examined and found satisfactory, also as the survey is incomplete pending the returned steam pipes in the cylinder room smoke boxes being dealt with. An amended interim certificate should be issued.

5/15/01 W.P.



© 2020

Lloyd's Register
Foundation