

11



Received from Chief Ship Surveyor..... 1 FEB 1960

SHIP NAME "ORION" REPORT Rot. No. 48691

SUBJECT TO permanent repairs to bottom shell standing Conditions of Class: plate in way of cofferdam between Nos. 4 & 5 D.B.tanks (p.s.) by the Special Durvey and to indented shell plates F.3 & 4 and G.5 (p.s.f) and locally doubled shell plates F.7 (p&sf) and welded shell plate A.1 (p.s.a) also lower rudder bushing being specially examined and dealt with as found necessary next drydocking. ACTION is DEFERRED for Special Survey by 5,60.

L. Appendix. (As before ~~xxxxxxxx~~)
Days due: SPECIAL SURVEY (C) due 5,59. Postponement until 5,60 approved 12.8.59 following a satisfactory G.E.

Area of Present Survey: (Afloat ~~and in dry dock~~)
Permanent repairs to collision damage.

Special Features:

Interim Certificate in order (Yes-~~No~~)

Items Outstanding: (If any for S.S.)
ALL ITEMS.

to be completed by: by 5,60.

Recommendation:
SUBJECT as above, but further ACTION continue to be DEFERRED for Special Survey by 5,60.

SUBJECT

~~IN S.R.L. APPENDIX.~~
Shell plate No.4 in 2nd below sheer (p.s.) indented.

*R. J. C.
29/1/60*



© 2020

Lloyd's Register Foundation

Blk(new)

This Certificate... While the... understood that... accuracy in any... or for any error... of the Society.

00100-005105-0016