

003100-00405-0072

Received from Chief Surveyors

E "JANBLEW" Report N.Os No. 5341

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case at the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

S.S. No. 3 for Classification ~~due~~ PARTLY HELD.

be completed not stated.

Solepiece of sternframe T.W. to be specially examined at next dry docking.

Pitted shell plating at light water line to be specially examined at the next dry docking.

Shell plating to be drilled at first available opportunity.

sert in S.R.L

Exd. 12.40 - for 12 mos.
Items as above.

OCKING DATE 12.40)

It is concluded the machinery spaces have been examined.

J.C.D.
4.3.41

[Signature]

see letter
11.9.41

© 2020

P.T.O. →

Lloyd's Register
Foundation