

Rpt. 8

Date of writing Report 24 SEP 1959 When handed in at Local Office 26.9.59 Port of ABERDEEN Received London 11 OCT 1959 No. 24636
Survey held at PETERHEAD No. of Visits 1 First Date and 19 Last Date 1 MAY 1959

REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 34245 on the Iron or Steel S.S. "TYNECASTLE"
Built at TROON By Whom Ailsa S.B. Co. Ltd. Tons gross 570
When 1924 - 12 Year Month
Owners CASTLE COASTERS LTD. Owners' address ---
(If not already in R.B.)
Managers --- Port of Registry Leith

Surveyed Afloat or in Drydock Afloat Name of Dock at Peterhead Date of last examn. in Drydock ---

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 115550 Port ---
To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS		Machinery	
Date of Special and of Drydocking Surveys, etc.			
<u>100A1</u>	<u>SS 11/54</u>	<u>LMC</u>	<u>ES 11/54</u>
<u>Reclassified 9/50</u>	<u>DS 9/56</u>	<u>MBS 8/58</u>	<u>TS(L) 9/56</u>
<u>NS</u>		<u>SPS 11/54</u>	

and references to any letters relating to this Report Abn-Lon 2.9.59.
Lon-Abn. 23.9.59.

Where cases where the Surveyor has not made a special damage report he should state whether he offered services for this purpose and to whom and why they were declined. Freeboard as marked in Register Book 4 ft 0 1/4 ins
Was a damage report made by anyone else? If so, by whom? ---

ATION AND REPAIRS AS PER RULE FOR COMMENCEMENT OF SPECIAL SURVEY "D" (due 11/58) - SHIP 34 YEARS OLD.

The survey held at this time constituted a preliminary examination of the hold, decks and engine boiler spaces in order to advise the Owners of the necessary preparations required in order to with the Special Survey.

Part of the hold ceiling was lifted but the structure could not be properly examined as the bottom was full of cargo residue and the steelwork in the hold found to be coated with heavy le.

It was recommended at this time that all spaces be thoroughly scaled and cleaned and sented for further examination. The remaining requirements of the Rules for Special Survey "D" e also made clear to the Owners.

Since this first visit, no further request to attend has been received and reference is w made to subsequent correspondence, copies of which are attached.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Fairied or Repaired								
Fairied or Repaired in place								

Has a Survey also been held on machinery of the Ship? NO Is Classification Certificate required? If so, to be sent to ---
If so, is the Report sent now, or when will it be sent? --- Has Interim Certificate been issued? ---

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

For the information of the Committee.

Geo Stuart
Surveyor to Lloyd's Register of Shipping

Date of Committee GLASGOW 30 SEP 1959

Minute Deferred for 55

Noted for Header

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR SURVEY

Have the spaces now surveyed been cleared and cleaned as necessary?.....

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?.....

Have the bilges been cleaned out and examined?.....

Has steelwork had rust removed and afterwards been recoated as necessary?.....

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?.....

Has a Load Line Survey been held?..... If so, state which.....

Have the shell and deck plating been drilled as per Rule?..... If so, Report 8(Dr) to be attached.....

Have any alterations to the approved scantlings and arrangements now been effected?..... If so, report details in body of Report.....

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word “Yes”, e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

The present condition of the following parts in so far as examined is to be reported:—

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? See Below

Travelling Expenses (if chargeable).....

Date when A/c. Rendered

Date when A/c. Rendered

Lloyd's Register
Foundation