

F.E.

ed by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Stl Se " TYNDALL,Rpt. Stl, No. 31054,

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

18' Long  
Transverse No. 3960,

Depth "d" ✓Framing: Table No. ✓Description Bull angle frames as approved,Longitudinal No. 12181,

Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{12.99 \text{ to m.o.}}{\quad}$

Deck Sheerstrake

as approved,

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel).

10\* (Stl) well D\*

Cell D.B. v E 23' f 151 368 t, D.T. f 107 t, F.P.T. 142 t, A.P.T. 28 t.

F.K, 5 B.H, pt cem, Lloyds ACP.

Q 138', B 16', F 21'.

machs aft.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register Foundation

003138-003146-0266