

29 APR 1963

Ship's name "AFRICAN REEFER" Port B.As No. 34904

Last survey date 11.3.63


Class is subject to

- 1) Starboard aft auxiliary engine entablature (~~Metallock~~ in way of No. 3 cylinder) being specially examined by 9.63.
- 2) Main standby cooling pump (~~Metallock~~) being examined by 9.63.
- 3) Starboard aft auxiliary engine (~~Metallock~~^{11/62} in way of No. 1 cylinder) being specially examined by 5.63.

Repairs

Metallock repairs and strap reinforcements of two small fractures in way of top flange of main engine No. 2 cylinder aft port column. Surveyor recommends main engine No. 2 cylinder after port column (~~Metallock~~^{3/63}) at the top flange being again examined by September 1963.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as above and as now recommended.



© 2020

Lloyd's Register
Foundation

25.4.63

003245-003251-0074