

11 DEC 1962

Ship's name **AFRICAN REEFER** Port No.

Last survey date

Class is subject to

1. S.A. aux. engine entablature (metelocked in way of N°3 cyl.) being specially examined by 9.63
2. main standby cooling pp. (metelocked) being examined by 9.63.

S.A. aux. engine found fractured on s.s. in way N°1 cylinder metelock repairs carried out. Surveyor recommends to be specially examined by 5.63.

It is submitted that this vessel is eligible to remain as CLASSED, subject as above and as recommended

WES

11/12/62

© 2020

Lloyd's Register
Foundation

003245-003251-0078