

Ship's name "THE PRESIDENT"

Port Grk.

No. 27200

This ship was built in 1936-5 and SPECIAL SURVEY (D) became due 6,63.

There is an Appendix Note.

The GREENOCK Surveyors report (12,62), ship examined on slipway after damage stated to have been caused by grounding, keel and bottom plating and internal structure in way of Nos.1 & 2 and feed water D.B.tanks reported to be indented and/or buckled.

Repairs have not been effected at this time as the Owners have sold the ship for breaking up purposes.

^{left}
~~laid up at~~ Port Glasgow for Troon where is to be broken up. ^{she}

IT IS ACCORDINGLY SUBMITTED
no further ACTION need be taken
meantime pending receipt of further
information as to the ship's
ultimate disposal.

IN S.R.L. APPENDIX.

Bottom plating slightly hogged.

S.R.L.
11/1/63



© 2020

Lloyd's Register
Foundation